



# ColorWash 1200E<sup>AT</sup>

## Photometric Diagrams



### FRESNEL LENS

Lamp: MSR 1200 SA



Beam angle 10° - LightMax Mode



Beam angle 13° - Min. zoom



Beam angle 44° - Max. Zoom




# ColorWash 1200E<sup>AT</sup>

## Photometric Diagrams


### WIDE-ANGLE LENS

Lamp: MSR 1200 SA


Beam angle 68° - Lightmax.mode




Distance=5m




Beam angle 75° - Min. Zoom




Distance=5m



Beam angle 87° - Max. Zoom



Distance=5m




# ColorWash 1200E<sup>AT</sup>

## Photometric Diagrams


### PC LENS

Lamp: MSR 1200 SA


Beam angle 10° - LightMax mode




Distance=5m




Beam angle 12° - Min. zoom



Distance=5m



Beam angle 36° - Max. Zoom



Distance=5m

